


Identification guide - affected RCBOs

The recall applies ONLY to the single module RCBOs with the reference numbers; **AD310T, AD316T, AD320T or AD325T.**

No other Hager RCBO or product is affected by the recall.

To help you identify these with certainty, we have highlighted the key distinguishing features.



PLEASE NOTE: It is highly recommended that identification of the recalled RCBO be confirmed by a qualified and licensed electrical contractor.

Please visit www.hagerelectro.com.au/6862.htm for more information or to register the location of RECALLED RCBO/s.